

Port Lincoln Town Jetty Salvaged Timber Availability

Lot #	Quality
<p data-bbox="97 293 172 322">Lot 1</p> 	Good
<p data-bbox="97 781 172 810">Lot 2</p> 	Good
<p data-bbox="97 1263 172 1292">Lot 3</p> 	Good
<p data-bbox="97 1729 172 1758">Lot 4</p> 	Good

Lot 5



Good

Lot 6



Good

Lot 7



Fair

Lot 8



Good

Lot 9



Good

Lot 10



Good

Lot 11








Good

Lot 12



Good

<p>Lot 13</p>  A close-up photograph of a stack of weathered wooden planks. A black strap is wrapped around the stack, and a white label is attached to it. The wood shows signs of aging and weathering.	<p>Good</p>
<p>Lot 14</p>  A close-up photograph of a stack of weathered wooden planks. A white label with the text "LOT 14" is attached to the stack. The wood is dark and shows signs of weathering.	<p>Good</p>
<p>Lot 15</p>  A close-up photograph of a stack of weathered wooden planks. A white label with the text "LOT 15" is attached to the stack. The wood is dark and shows signs of weathering.	<p>Good</p>
<p>Lot 16</p>  A close-up photograph of a stack of weathered wooden planks. A white label with the text "LOT 16" is attached to the stack. The wood is dark and shows signs of weathering.	<p>Good</p>
<p>Lot 17</p>  A close-up photograph of a stack of weathered wooden planks. A white label with the text "LOT 17" is attached to the stack. The wood is dark and shows signs of weathering.	<p>Fair</p>

Lot 18



Fair

Lot 19



Fair

Lot 20








Good

Lot 21




Fair

<p>Lot 22</p> 	<p>Fair</p>
<p>Lot 23</p> 	<p>Fair</p>
<p>Lot 24</p> 	<p>Fair</p>
<p>Lot 25</p> 	<p>Good</p>
<p>Lot 26</p> 	<p>Good</p>

Lot 27	 A photograph showing a stack of weathered wooden planks. A white label is attached to the stack with a black strap. The planks are stacked horizontally and show signs of aging and weathering.	Good
Lot 28	 A photograph showing a stack of weathered wooden planks. A white label is attached to the stack. The planks are stacked horizontally and show signs of aging and weathering.	Good
Lot 29	 A photograph showing a stack of weathered wooden planks. A white label is attached to the stack with a black strap. The planks are stacked horizontally and show signs of aging and weathering. A small wooden block is visible between the planks.	Good
Lot 30	 A photograph showing a stack of weathered wooden planks. A white label is attached to the stack with a black strap. The planks are stacked horizontally and show signs of aging and weathering. A red stripe is visible on the side of the planks.	Good
Lot 31	 A photograph showing a stack of weathered wooden planks. Two white labels are attached to the stack. The planks are stacked horizontally and show signs of aging and weathering. A red stripe is visible on the side of the planks.	Good

Lot 32



Good

Lot 33



Fair

Lot 34




Good

Lot 35



Good

Lot 36



Good

Lot 37



Good

Lot 38



Good

Lot 39



Good

Lot 40



Good

Lot 41



Good

Lot 42



Good

Lot 43



Fair

Lot 44



Good

Lot 45



Fair

Lot 46

Fair



Lot 47

Fair



Lot 48

Good



Lot 49



Good

Lot 50



Fair

Lot 51



Good

Lot 52



Excellent

Lot 53



Excellent

Lot 54



Excellent

Lot 55

Good



Lot 56

Excellent



Lot 57

Excellent



Lot 58



Excellent

Lot 59



Fair

INDIVIDUAL TIMBERS FOR SALE Examples Only



INDIVIDUAL TIMBERS FOR SALE Examples Only

